



# 1234 Anywhere Street Houston, TX 77000

## Prepared for: John Doe

Inspector: David Rogers T.R.E.C.: #5048

Date: 02/13/2023



# **PROPERTY INSPECTION REPORT FORM**

John Doe	02/13/2023
Name of Client	Date of Inspection
1234 Anywhere Street, Houston, TX 77000 Address of Inspected Property	
David Rogers	5048
Name of Inspector	TREC License #
Name of Sponsor (if applicable)	TREC License #

## PURPOSE OF INSPECTION

A real estate inspection is a visual survey of a structure and a basic performance evaluation of the systems and components of a building. It provides information regarding the general condition of a residence at the time the inspection was conducted. It is *important* that you carefully read ALL of this information. Ask the inspector to clarify any items or comments that are unclear.

## **RESPONSIBILITY OF THE INSPECTOR**

This inspection is governed by the Texas Real Estate Commission (TREC) Standards of Practice (SOPs), which dictates the minimum requirements for a real estate inspection.

The inspector IS required to:

- use this Property Inspection Report form for the inspection;
- inspect only those components and conditions that are present, visible, and accessible at the time of the inspection;
- indicate whether each item was inspected, not inspected, or not present;
- indicate an item as Deficient (D) if a condition exists that adversely and materially affects the performance of a system or • component **OR** constitutes a hazard to life, limb or property as specified by the SOPs; and
- explain the inspector's findings in the corresponding section in the body of the report form.

The inspector IS NOT required to:

- identify all potential hazards;
- turn on decommissioned equipment, systems, utilities, or apply an open flame or light a pilot to operate any appliance;
- climb over obstacles, move furnishings or stored items;
- prioritize or emphasize the importance of one deficiency over another; •
- provide follow-up services to verify that proper repairs have been made; or •
- inspect system or component listed under the optional section of the SOPs (22 TAC 535.233). •

## **RESPONSIBILITY OF THE CLIENT**

While items identified as Deficient (D) in an inspection report DO NOT obligate any party to make repairs or take other actions, in the event that any further evaluations are needed, it is the responsibility of the client to obtain further evaluations and/or cost estimates from qualified service professionals regarding any items reported as Deficient (D). It is recommended that any further evaluations and/or cost estimates take place prior to the expiration of any contractual time limitations, such as option periods.

Please Note: Evaluations performed by service professionals in response to items reported as Deficient (D) on the report may lead to the discovery of additional deficiencies that were not present, visible, or accessible at the time of the inspection. Any repairs made after the date of the inspection may render information contained in this report obsolete or invalid.

#### **REPORT LIMITATIONS**

This report is provided for the benefit of the named client and is based on observations made by the named inspector on the date the inspection was performed (indicated above).

ONLY those items specifically noted as being inspected on the report were inspected.

This inspection IS NOT:

- a technically exhaustive inspection of the structure, its systems, or its components and may not reveal all deficiencies;
- an inspection to verify compliance with any building codes;
- an inspection to verify compliance with manufacturer's installation instructions for any system or component and DOES NOT imply insurability or warrantability of the structure or its components.

## NOTICE CONCERNING HAZARDOUS CONDITIONS, DEFICIENCIES, AND CONTRACTUAL AGREEMENTS

Conditions may be present in your home that did not violate building codes or common practices in effect when the home was constructed but are considered hazardous by today's standards. Such conditions that were part of the home prior to the adoption of any current codes prohibiting them may not be required to be updated to meet current code requirements. However, if it can be reasonably determined that they are present at the time of the inspection, the potential for injury or property loss from these conditions is significant enough to require inspectors to report them as Deficient (D). Examples of such hazardous conditions include:

- malfunctioning, improperly installed or missing ground fault circuit protection (GFCI) devices and arc-fault devices;
- ordinary glass in locations where modern construction techniques call for safety glass;
- malfunctioning or lack of fire safety features such as, smoke alarms, fire-rated doors in certain locations, and functional emergency escape and rescue openings in bedrooms;
- malfunctioning carbon monoxide alarms;
- excessive spacing between balusters on stairways and porches;
- improperly installed appliances;
- improperly installed or defective safety devices;
- lack of electrical bonding and grounding; and
- lack of bonding on gas piping, including corrugated stainless steel tubing (CSST).

Please Note: items identified as Deficient (D) in an inspection report DO NOT obligate any party to make repairs or take other actions. The decision to correct a hazard or any deficiency identified in an inspection report is left up to the parties to the contract for the sale or purchase of the home.

## This property inspection report may include an inspection agreement (contract), addenda, and other information related to property conditions.

INFORMATION INCLUDED UNDER "ADDITIONAL INFORMATION PROVIDED BY INSPECTOR", OR PROVIDED AS AN ATTACHMENT WITH THE STANDARD FORM, IS NOT REQUIRED BY THE COMMISSION AND MAY CONTAIN CONTRACTUAL TERMS BETWEEN THE INSPECTOR AND YOU, AS THE CLIENT. THE COMMISSION DOES NOT REGULATE CONTRACTUAL TERMS BETWEEN PARTIES. IF YOU DO NOT UNDERSTAND THE EFFECT OF ANY CONTRACTUAL TERM CONTAINED IN THIS SECTION OR ANY ATTACHMENTS, CONSULT AN ATTORNEY.

## ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

This report provided by the Company contains the good faith opinion of the inspector concerning the observable need, if any, on the day of the inspection, for the repair, replacement, or further evaluation by experts of the items inspected. Unless specifically stated, the report will not include and should not be read to indicate opinions as to the environmental conditions, presence of toxic or hazardous waste or substance, whether or not the property lies within a flood plane or flood prone area, whether or not property lies within or in close proximity of a geological fault, presence of termite or other wood-destroying organisms, or compliance with local codes, ordinances, statutes or restrictions or the insurability, efficiency, quality, durability, future life or future performance of any item inspected.

The Company makes no guarantee or Warranty as to any of the following:

- *I.* That all defects have been found or that company will pay for repair of undisclosed defects.
- II. That any of the items inspected are designed or constructed in good and workmanlike manner.
- III. That any of the items inspected will continue to perform in the future as they are performing at the time of the inspection.
- IV. That any of the items inspected are merchantable or fit for any particular purpose.

With any visual inspection, it is impossible to assess the full extent of any noted discrepancy. No destructive testing or dismantling of building components is performed. However, the information provided in this report is intended to help you identify the problem areas. If necessary, a detailed, in depth examination by a qualified professional should be obtained to determine the full extent and cause of any noted problem.

The information contained in this report is based on a visual observation of the property and is designed to be clear and easy to understand. The comments are an opinion of the observations, determinations, or findings as defined by the Texas Real Estate Commission (TREC)-Real Estate Inspectors Standards of Practice (§535.227-§535.233) and are not intended to be, nor are they, a definitive summary of the recommended repairs. All structures are in need of some repair. It is not the responsibility of the inspector to make recommendations to the client regarding the purchase of the property, only to observe and report. The condition of the property is based on the client's own value system, not the inspectors.

The following descriptions are used to identify comments in this report:

#### Systems and Topic Headings:

Texas Real Estate Commission Property Inspection Report Form REI 7-6 (Revised 8/9/21)

#### Note:

General information and or observations for client awareness of conditions that may not necessarily warrant immediate attention.

#### **Deficiencies:**

A condition that adversely and materially affects the performance of a system, or component; or constitutes a hazard to life, limb, or property as specified by these standards of practice.

Front, Rear, Left and Right: Denotes location by facing the property from the street.

Check boxes are used to denote location, identification purposes and items that are listed as deficient.


## Conditions at the time of inspection:

Present at Inspection:	🗹 Buyer	✓ Selling Agent	Listing Agent	Occupant
Building Status:	🗹 Vacant	Owner Occupied	Tenant Occupied	Other
Weather Conditions:	🗹 Fair	Cloudy	🗆 Rain	63 Outside Temp.
Utilities On:	🗹 Yes	No Water	No Electricity	🗆 No Gas
Special Notes: New Con	nstruction			
Inaccessible or obs	tructed areas:			

Sub Flooring	Attic Space is Limited - Viewed from Accessible Areas
Floors Covered	Plumbing Areas - Only Visible Plumbing Inspected
Walls/Ceilings Covered or Freshly Painted	Siding Over Older Existing Siding
Behind/Under Furniture and/or Stored Items	Crawl Space is limited - Viewed From Accessible Areas
Madel/Milden investigations and NOT is shall doubt	this was set it is becaused the second of this is successful at the second

Mold/Mildew investigations are NOT included with this report; it is beyond the scope of this inspection at the present time. Any reference of water intrusion is recommended that a professional investigation be obtained.

### NOTICE: THIS REPORT IS PAID FOR BY AND PREPARED FOR THE CLIENT NAMED ABOVE. THIS REPORT IS NOT VALID WITHOUT THE SIGNED SERVICE AGREEMENT AND IS NOT TRANSFERABLE.



TREC Form No. OP-I

I=Inspected	NI=Not Inspected	NP=Not Present	<b>D=Deficient</b>	
I NI NP D				
	I.	STRUCTURAL SYS	TEMS	

### $\bigtriangledown$ $\Box$ $\Box$ $\checkmark$ A. Foundations

Type of Foundation(s): Slab on Grade

Comments:

**Note:** It is not within the scope of this inspection to enter a crawl space or any area where headroom is less than 18 inches or the access opening is less than 24 inches wide and 18 inches high; provide an exhaustive list of indicators of possible adverse performance; or inspect retaining walls not related to foundation performance.

#### Foundation Performance Opinion:

 $\checkmark$  The dwelling did not exhibit any evidence of major foundation deformities caused from excessive foundation settlement at the time of inspection.

Most of the greater Houston area soil is an expansive type clay. Therefore, proper care of the soil under your home's foundation is very important in preserving the integrity of the structure. Clay soils have the ability to expand (when wet) or to contract (when dry) at alarming rates. This requires that an even and rather constant level of moisture be maintained around the entire house. Defects in the foundation occur when the structure does not move as a unit. This could occur when one area around the foundation is continually wet, while other areas remain dry.

Trees and vegetation in close proximity around the dwelling can also have adverse effects on the soils supporting the slab footings and adjacent flatwork. Large trees and dense vegetation can draw excessive amounts of moisture from the soils around and under the slab. In addition to water absorption, the root systems can cause differential movement under the slab and surrounding flatwork.

**Foundation Performance Note:** Weather conditions, drainage, underground leaks, erosion, trees/vegetation, and other adverse factors can effect the structure allowing differential movement to occur. This inspectors opinion is based on visual observations of accessible and unobstructed areas of the structure at the time of the inspection. Future performance of the structure cannot be predicted or warranted. This was not a structural engineering survey nor was any specialized testing done of any sub-slab plumbing systems during this limited visual inspection. In the event that structural movement is observed, the client is advised to consult with a Structural Engineer or foundation specialist who can isolate and identify causes, and determine what corrective steps, if any, should be considered to either correct and/or reduce structural movement.

**Observations of Structural Movement or Settlement:** 

No indications of defects observed at the time of inspection.

Foundation Deficiencies:

- Exposed buckle nails observed at the following locations: front wall front guest bedroom at the interior corner.
- Honeycomb observed at the perimeter of the slab at the following locations: rear patio surface.
- Corner fracture or corner missing observed at the following locations: right rear corner breakfast room, right rear corner master bedroom.
- Spalling of the slab surface observed at the following locations: garage front wall, garage rear wall.

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				



Honeycomb rear patio slab



Exposed buckle nail front guest bed at corner



Corner missing right rear breakfast room slab



Corner missing right rear master bedroom slab



Concrete spall front garage stem wall



Concrete spall slab rear garage wall

## ☑ □ □ ☑ B. Grading and Drainage

#### Comments:

**Note:** It is not within the scope of this inspection to inspect flatwork or detention/retention ponds (except as related to slope and drainage); determine area hydrology or the presence of underground water; or determine the efficiency or performance of underground or surface drainage systems.

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			

## Grading and Drainage Deficiencies:

- Evidence of standing or ponding water at the following locations: rear yard along the rear fence at several places, left dwelling.
- High soil levels observed at the following locations: right dwelling.
- **I** Leaves and debris observed at the gutters.
- Standing water observed in the gutters at the following locations: right garage gutter.



Evidence of ponding water left dwelling



Debris gutters



Standing water right garage gutter



High soils right dwelling

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			



Evidence of ponding water rear yard



Evidence of ponding water rear yard

**Note:** Drainage piping installed below grade at the front exterior. It was not determinable at the time of inspection if the drain line is clear and functioning properly.

**Suggested Grading and Drainage Maintenance:** Grading around the dwelling should slope away from the structure, 6 inches per 10 feet. Excess runoff should drain to adjacent right-of-ways, swales or culverts. Allowing excess runoff to collect and stand around the dwelling will effect the soil conditions around the structure which may result in differential movement.

Most of the greater Houston area soils contain expansive clays. Therefore, proper care of the soil under and around your home's foundation is very important in preserving the integrity of the structure. Implementing drainage provisions and a watering program around the perimeter of the dwelling will help to stabilize soil conditions and reduce the risk of abnormal differential movement.

## ☑ □ □ ☑ C. Roof Covering Materials

Types of Roof Covering: Composition Shingles

Viewed From: Ground Level and Ladder Level

Comments:

**Note:** It is not within the scope of this inspection to determine the remaining life of the roof covering, age of the roof covering, identify latent hail damage, determine the number of layers of roof covering material, exhaustively examine all fasteners and adhesions, or provide an exhaustive list of previous repairs and locations of water penetrations. The roof covering will be viewed from the ground if the inspector may damage the roof covering or cannot safely reach or stay on the roof surface.

## Roof Performance Opinion:

 $\blacksquare$  The roof covering is experiencing normal wear.

Roof Covering Deficiencies:

- Raised shingle tabs or debris under the shingle tabs at the following locations: rear slope at the range hood vent roof jack.
- ☑ Damaged shingles observed at the following locations: ear slope at the range hood vent roof jack, left slope at the front bathroom exhaust fan roof jack.
- Foot traffic damage observed at the roof covering at the following locations: front porch roof left slope.
- Shingles observed cupping at the roof covering at the right slope, rear roof slope and front

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			

valley. Shingle tabs that do not properly lay down and seal over time are more susceptible to moisture intrusion and wind damage under certain weather conditions.


- Kickout flashing missing at the following locations: garage right roof slope at the front dining room wall.
- Kickout flashings not caulked at the roof eaves
- Caulk face nailed roof jacks where missing at the following locations: bathroom fan roof jacks, right slope clover roof jack.
- Shingles not properly installed of the sides of the roof jacks at the following locations: rear roof slope.
- **I** Roof jacks improperly installed at the following locations: both water heater vents.
- Construction debris observed at the roof covering.



Raised shingle surface, cracked tap range hood



Cupping shingles right roof slope



Cupping shingles right roof slope



Cupping shingles front roof slope

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			




Kickout flashing not caulked at stucco



Kickout flashing missing garage roof at wall



Construction debris left roof slope



Foot traffic damage shingles front porch roof



Construction debris left roof slope



Improper shingle installation furnace roof jack

```
I=Inspected
                     NI=Not Inspected
                                               NP=Not Present
```



Improper shingle installation furnace roof jack



Shingles not installed over sides rear roof jack



Damaged shingle tab left slope roof jack



Cupping shingles rear roof slope



Caulk face nailed roof jacks



Caulk face nailed roof jacks

 $\square$   $\square$   $\square$   $\square$   $\square$  D. Roof Structures and Attics

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
	Viewed From: Attic Decking		

Approximate Average Depth of Insulation Attic Floor: 9"

Approximate Average Depth of Insulation Attic Walls: 4"

Insulation Type: Loose Fill

Comments:

**Note:** It is not within the scope of this inspection to enter attics and unfinished spaces where access is less than 22" x 30", head room less than 30", operate power ventilators, or provide an exhaustive list of locations of water penetrations.

## **Insulation Deficiencies:**

- ☑ Inadequate insulation depth at the attic floor. An insulation depth that will provide an R-30 to R-38 at the attic floor will improve the efficiency of the dwelling. There was not an insulation specification sheet installed at the attic to verify product R values.
- Redistribute insulation where missing or moved at the attic floor.
- Insulation batts improperly installed. Craft paper side should face the conditioned space at the attic walls.



Redistribute insulation where moved at attic



Insulation batts installed improperly attic walls



Redistribute insulation where moved at attic



Insulation batts installed improperly attic walls

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			



Redistribute insulation where moved at attic



Redistribute insulation where moved at attic

## Ventilation Deficiencies:

- $\checkmark$  Ventilation baffles missing at the eaves of the attic to prevent loose fill insulation from blocking the soffit vents.
- Mechanical attic ventilation devices not properly positioned above the roof decking opening at the following locations: left roof slope.
- Debris in the mechanical attic vent fan at the following locations: left attic slope.



Attic mechanical fan not positioned over hole



Debris in the attic mechanical fan



I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			

Ventilation baffles missing at attic soffits

**Note:** Attic electric power ventilation devices were not accessible at the time of inspection, were not operated and could not be inspected for proper performance.

Attic Framing Deficiencies:

No indications of defects observed at the time of inspection.

**Attic Access Deficiencies:** 

- Disappearing attic access ladder frame is not poly sealed at the attic structure.
- Disappearing attic access ladder frame is improperly secured to the framed opening. Refer to manufacturers specifications for proper fasteners.
- ☑ Disappearing attic access ladder is not properly trimmed. Gaps are present at the ladder joints when extended.
- Service access flooring to the equipment in the attic is not properly secured.
- Service access flooring thickness is undersized at the attic.
- Gaps in the service access flooring to the equipment in the attic observed at the following locations: water heater and furnaces.
- Service access flooring to the equipment should be unobstructed.



Attic ladder not properly trimmed



Improper fasteners at attic ladder frame



Attic ladder not poly sealed at ceiling joists



Gaps attic decking at water heater

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			



Attic deck undersized at water heater



Attic deck not clear of obstructions



Gaps attic deck at furnaces



Loose attic decking at several locations

## ☑ □ □ ☑ E. Walls (Interior and Exterior)

### Comments:

**Note:** It is not within the scope of this inspection to report cosmetic damage or the condition of the wall coverings; paints, stains or other surface coatings; cabinets; or countertops; report the condition or presence of awnings; or provide an exhaustive list of locations of water penetrations.


#### Interior Wall Deficiencies:

- Cracks in the drywall observed at the following locations: family room at the fireplace gas valve.
- Holes in the drywall observed at the following locations: dryer vent pipe at the utility room.
- Cabinet doors binding at the following locations: kitchen sink left door at the dishwasher, kitchen upper cabinet right of the double ovens, master bathroom right sink right door.
- ☑ Clothes rods not secured rear guest bedroom closet.

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			



Kitchen cabinet door binding at dishwasher



Hole drywall at dryer vent pipe



Clothes rods not secured rear guest bed closet



Kitchen cabinet door binding at oven



Drywall cracks at fireplace gas valve



Master bathroom cabinet door binding

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
	122.23		



Backsplash tile missing at receptacle



Backsplash tile missing at GFCI receptacle

## Exterior Wall Materials:

□ Brick       □ Stone       ☑ Wood       ☑ Stucco Veneer       □ Composite Siding         □ Vinyl       □ Aluminum       □ Asbestos       ☑ Cement Board       □ Other:	Exterior	wall waterials.				
$\Box$ Vinyl $\Box$ Aluminum $\Box$ Asbestos $\blacksquare$ Cement Board $\Box$ Other:	🗆 Brick	□ Stone	🗹 Wood	🗹 Stucco Veneer	□ Composite Siding	
	🗆 Vinyl	🗆 Aluminum	□ Asbestos	☑ Cement Board	□ Other:	

## **Exterior Wall Deficiencies:**

- Seal around penetrations at the exterior walls where missing or deteriorated at the following locations: ground conductor left garage, ground conductor left garage, sprinkler conduit front garage.
- ☑ Vertical trim caulking missing or deteriorated at the following locations: roof eave fascia where terminated at the stucco veneer.
- Z-flashing drainage plane is covered with caulk above the windows.
- ✓ No drainage plane observed at the base of the stucco veneer overhangs at the following locations: front porch entry arch, rear patio beams. The absence of a drainage plane can cause moisture to become entrapped behind the stucco veneer and cause deterioration to the substrate.
- Z-flashing not visible at the stucco veneer above the front entry arched window.
- Z-flashing not properly installed above the doors at the following locations: front entry door, rear patio door, double car garage door, golf cart garage door, left garage door.
- Stucco brick cap not sealed along the top above the garage doors.
- Stucco installed with less than 2" of clearance of the flatwork or slab surface at the following locations: front porch walls, front porch columns, rear patio columns.

I=Inspected	NI=Not Inspected	NP=Not Present	<b>D=Deficient</b>	
I NI NP D				



Stucco clearance front porch columns



Stucco clearance front porch walls



No z-flashing above front entry door



Z-flashing missing above entry arched window



Z-flash drainage plane caulked above windows



Z-flashing missing above garage door

I=Inspected	NI=Not Inspected	NP=Not Present	<b>D=Deficient</b>	
I NI NP D				



Z-flashing missing above rear patio door




Seal penetration grounding conductor




Seal penetration sprinkler conduit



Z-flashing missing above left garage door



Seal penetration grounding conductor



Caulk fascia at stucco

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			



Brick not sealed above garage door



No drainage plane front porch arch



No drainage plane at rear patio beams



Stucco clearance base rear patio columns

## $\square$ $\square$ $\square$ $\square$ F. Ceilings and Floors

#### Comments:

**Note:** It is not within the scope of this inspection to report cosmetic damage or the condition of the ceiling coverings; paints, stains or other surface coatings; or provide an exhaustive list of locations of water penetrations.

#### **Ceiling Deficiencies:**

No indications of defects observed at the time of inspection.

#### Floor Deficiencies:

No indications of defects observed at the time of inspection.

## 

#### Comments:

**Note:** It is not within the scope of this inspection to determine the cosmetic condition of paints, stains or other surface coatings, report the condition of security devices, or operated door locks if the key is not provided.

## Interior Door Deficiencies:

☑ Doors do not properly latch at the following locations: guest bedroom hallway closet, master bedroom.

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			

- **Doors** misaligned or binding at the door jamb at the following locations: kitchen pantry, office closet.
- Door drags the finish floor at the following locations: rear guest bedroom closet, rear guest bedroom door.
- Privacy lock not functioning properly at the following locations: office half bathroom door.

**Door hinge fasteners missing at the following locations: office door.** 





Door not latch guest bed hallway closet





Door drags floor rear guest bed closet



Hinge fasteners missing office door



Page 21 of 44 Promulgated by the Texas Real Estate Commission • (512) 936-3000 • www.trec.texas.gov

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			

## Door binding office closet



Door not latching master bedroom

## Privacy lock not working office bathroom door



Door drags floor rear guest bedroom

## Exterior Doors Deficiencies:

Door casing not caulked at the threshold at the following locations: left garage door.

Door lock and latch are not properly aligned at the following locations: garage entry door



Threshold not caulked left garage door



Lock and latch not aligned garage entry door

## Garage Doors Deficiencies:

Type of Door(s): Metal

☐ Fiberglass

Garage door jambs end cuts not properly painted to protect from weathering.

Garage door jambs not tight with the side stem walls.

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			



Garage door jamb end cuts not properly painted



Gaps garage door jamb and slab stem walls

## $\square$ $\square$ $\square$ $\square$ H. Windows

Comments:

**Note:** Only accessible windows were operated at the time of inspection. It is not within the scope of this inspection to report the condition of awnings, blinds, shutters, security devices or other non-structural systems; exhaustively observe insulated windows for broken seals, glazing for identifying labels, or identify specific locations of damage; or provide an exhaustive list of locations of deficiencies and water penetrations.

## Window Deficiencies:

✓ Window drainage ports missing covers at the following locations: front entry windows, dining room, office, master bathroom, master commode, master closet, master bedroom, family room breakfast room, rear guest bedroom, front guest bedroom, garage.



Drain port covers missing at several windows



Drain port covers missing at several windows

□ ☑ ☑ □ I. Stairways (Interior and Exterior)

Comments:

## ✓ □ □ J. Fireplaces and Chimneys

Comments:

**Note:** It is not within the scope of the inspection to verify the integrity of the flue, perform a chimney smoke leakage. Therefore, you may wish to obtain the services of a professional chimney sweep for these inspections and other services related to the fireplace and or chimney.

Report Identification	<u>1234 Anywhere Street, Hou</u>			
I=Inspected	NI=Not Inspected	NP=Not Present	<b>D=Deficient</b>	
I NI NP D				
	Type of Fireplace: Factor Flue penetration accessib Gas Valve Location: Left Gas Key Present: Yes	ble at the attic: No		
	Fireplace Deficiencies			
	No indications of defects	observed at the time of i	nspection.	
Ø □ □ □ к.	<b>Porches, Balconies, Decks, a</b> <i>Comments</i> :	nd Carports		

**Note:** It is not within the scope of this inspection to exhaustively measure every porch, balcony, deck or attached carport components; enter any area where headroom is less than 18" or the access opening is less than 24" wide x 18" high.

#### Porches, Balconies, Decks, and Carports Deficiencies:

No indications of defects observed at the time of inspection.

## II. ELECTRICAL SYSTEMS

## ☑ □ □ ☑ A. Service Entrance and Panels

#### Comments:

**Note:** It is beyond the scope of the inspection to determine present or future sufficiency of service capacity amperage, voltage, or the capacity of the electrical system; test arc fault circuit interrupter devices when the property is occupied or damage to personal property may result, in the inspector's reasonable judgment; conduct voltage drop calculations; determine the accuracy of overcurrent device labeling; remove covers where hazardous as judged by the inspector; operate overcurrent devices.

Service-Entrance Type: Below Ground

#### Service-Entrance Deficiencies:

Proper clearance not installed at the meter enclosure and exterior veneer. Min 1/4" clearance is required between electrical enclosures and the supporting wall on exterior installations. The meter enclosure should not be caulked blocking the required air space at the exterior veneer.



Required air space caulked at meter cabinet

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			

Service Equipment Disconnecting Means Enclosure: Midwest Enclosure Service Equipment Main Breaker Installed: 200 Amps

Service Equipment Disconnecting Means Deficiencies:


- ✓ Proper clearance not installed at the service equipment disconnecting means panelboard enclosure and exterior veneer. Min 1/4" clearance required in wet/damp locations. The panel cabinet should not be caulked at the exterior veneer.
- **I** The service equipment disconnecting means panelboard enclosure is not properly labeled.
- $\square$  The service equipment disconnecting means panelboard conduit is not tight at the enclosure. Rain water can enter the panelboard.
- ☑ The black insulated conductor used for grounding and or bonding should be marked green.



Required air space caulked at panelboard



Label missing dead front cover



Service conduit not tight, water entry possible



Black sheathed grounds not marked green

Service-Entrance Equipment Grounding and Bonding:

Grounding and Bonding Deficiencies:

- ☑ The grounding electrodes should be driven to below top surface of the soil.
- ☑ The metal gas distribution pipe entering the building should be bonded to the electrical system. The metal gas pipe is not bonded or could not be verified at the time of inspection.

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			



Ground rods not driven below grade

Branch Circuit Distribution Panelboard: Eaton Load Center Branch Circuit Distribution Panelboard Disconnect (at Service Panelboard): 200 amps

#### **Branch Circuit Distribution Panelboard Deficiencies:**

- The branch circuit distribution panelboard service conduit is missing the lug nut.
- The branch circuit conductors are bundled and not individually secured to the branch circuit distribution panelboard enclosure.
- ✓ The exposed service lugs are missing covers at the branch circuit distribution panelboard enclosure.
- $\square$  No bushing installed at the branch circuit conductors entry at the bottom of the branch circuit distribution panelboard enclosure.
- Debris observed at the interior of the branch circuit distribution panelboard enclosure.
- ✓ Improper sized circuit breaker installed, 20 amp breaker on 14 gauge wire. Labeled dining lights.
- ☑ The black insulated conductor used for grounding and or bonding should be marked green.
- ☑ The grounding bus bars are not interconnected at the service equipment disconnecting means panelboard enclosure. The panelboard should not be used as a conductor.
- Neutral and grounding terminals are in common at the branch circuit distribution panelboard enclosure. The bonding screw is installed at the neutral terminal bar which should be isolated from the branch circuit distribution panelboard enclosure cabinet.
- Combination arc fault breakers are not installed at the following locations: kitchen vent hood, kitchen GFCI.


I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			



Arc fault breakers missing kitchen



Service lug covers missing



Ground bars not interconnected panel



Branch circuits bundled top panelboard



Black sheathed grounds not marked green




Bushings missing bottom panelboard

I=Inspected	NI=Not Inspected
I NI NP D	



NP=Not Present

Debris bottom panelboard



Bond screw not removed from neutral bar



Service conduit lug missing

**D=Deficient** 



20 amp circuit breaker on 14 gauge wire

## ☑ □ □ ☑ B. Branch Circuits, Connected Devices, and Fixtures

Type of Wiring: Copper Wiring

## Comments:

**Note:** It is not within the scope of this inspection to inspect low voltage wiring; disassemble mechanical appliances; verify effectiveness of smoke alarms; verify interconnectivity of smoke alarms; activate smoke or carbon monoxide alarms that are or may be monitored or require the use of codes; verify that smoke alarms are suitable for the hearing-impaired; remove the covers of junction, fixture, receptacle or switch boxes unless specifically required by the inspection standards of practice.

In occupied dwellings some of the electrical outlets may be covered and inaccessible at the time of inspection. Only accessible electrical outlets will be inspected. Personal belongings, occupied receptacles, stored items and furniture will not be adjusted or moved by the inspector to gain access.

## Branch Circuit Deficiencies:

- ☑ No Ground Fault Circuit Interrupter protection present at the following locations: utility room dryer circuit breaker, utility room washing machine receptacle, utility room ironing board receptacle, kitchen dishwasher, master bathroom TV receptacle, attic receptacles.
- ✓ The electrical fixture boxes should be flush mounted with the face of combustible materials or installed with box extenders at the following locations: kitchen cooktop. This is a possible fire hazard.

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			

- ☑ The electrical fixture boxes should not be recessed more than 1/4" deep at the following locations: kitchen backsplash outlets.
- ✓ Proper clearance not installed at the A/C disconnect and left exterior veneer. Min 1/4" clearance is required between electrical enclosures and the supporting wall on exterior installations. The A/C disconnect should not be caulked blocking the required air space at the exterior veneer.
- $\checkmark$  Receptacle installed at the right side of the kitchen island is under an overhang that extends more than 6".
- ☑ Label all GFCI protected outlets where missing at the following locations: kitchen, utility room, garage, master bathroom receptacle under the vanity.
- **I** Light bulb not installed at the following locations: utility room ironing board.
- Motion light fixtures not responding at the front and rear dwelling.
- Conduit missing on electrical Romex wiring at the following locations: under the kitchen sink.



Receptacle under island overhang > 6"



Spark rings missing kitchen backsplash outlets



Conduit missing kitchen sink wiring



Spark ring missing kitchen cooktop

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				



Required air space caulked at A/C disconnects



Dryer circuit breaker not GFCI protected



Dishwasher circuit breaker



Light missing ironing board fixture



Washing machine receptacle not GFCI



Ironing board receptacle not GFCI

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				
				500



Master bathroom TV receptacle not GFCI



Attic receptacles not GFCI

Smoke and Fire Alarms Deficiencies:

**Note:** The dwelling smoke and or carbon monoxide detectors are manually tested. The test verifies that the siren is working and audible. The test button does not verify if the smoke and or carbon monoxide sensors are functioning properly. The age of the device can affect the function of the sensors and the age of each device is not verified. Refer to manufacturers specifications for recommendations on when the devices should be replaced. Deficiencies, if any, are notated below.

✓ Carbon monoxide alarm not installed at the exterior of the rear guest bedroom. An approved carbon monoxide alarm shall be installed outside of the each separate sleeping area in the immediate vicinity of the bedrooms in dwelling units within which fuel fired appliances are installed and in dwelling units that have attached garages.



Smoke alarm not CO exterior rear bed

## **Doorbell Deficiencies:**

No indications of defects observed at the time of inspection.

## III. HEATING, VENTILATION AND AIR CONDITIONING SYSTEMS

☑ □ □ ☑ A. Heating Equipment

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			

Type of Systems: Central Energy Sources: Gas Comments:

**Note:** The visual inspection of the heating equipment does not include internal parts that require dissembling of the unit to visually inspect. The condition of the heating equipment is based on the performance of the system when tested and those components that are visually accessible at the time of inspection. Full evaluation of the integrity of such components as a heat exchanger, require dismantling of the furnace and is beyond the scope of a visual inspection. The inspector is not required to program digital thermostats or controls; operate setback features on thermostats or controls; verify the accuracy of thermostats; inspect winterized or decommissioned equipment; inspect radiant heaters, steam heat systems, or unvented gas-fired heating appliances; inspect heat reclaimers, wood burning stoves, boilers, oil-fired units, supplemental heating appliances, de-icing provisions; determine the integrity of the heat exchanger; compatibility of components; and the sizing, efficiency, or adequacy of the systems.

## Temperature Differential:


When tested the air temperature differential observed between air supply and air return was 44 degrees at the left dwelling furnace and 40 degrees at the right dwelling furnace. (30-60 degrees normal range)

### Heating Equipment Deficiencies:

- ✓ The furnace vent pipe does not extend the proper distance above roof covering. The roof pitch is approximately 10/12. The IRC vent chart requires the bottom opening of the vent pipe be installed at least 2.5 feet above the roof surface.
- **Provide a set of the set of the**
- ☑ The furnace junction box knockouts are not properly covered inside both furnace cabinets.



Furnace vent pipes too short for roof slope



Knockout not covered furnace junction box

NI=Not Inspected

```
I=Inspected
I NI NP D
```

```
<section-header><section-header><section-header><section-header><section-header>
```

NP=Not Present

Left furnace labeling



Right furnace labeling



Debris inside left furnace cabinet

**D=Deficient** 



Debris inside right furnace cabinet



Knockout not covered furnace junction box

## ☑ □ □ ☑ B. Cooling Equipment

Type of Systems: Central

Comments:

**Note:** The visual inspection of the cooling equipment does not include internal parts that require dissembling of the unit to visually inspect. The condition of the cooling equipment is based on the

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			

performance of the system when tested and those components that are visually accessible at the time of inspection. Full evaluation of components requiring dismantling of the equipment is beyond the scope of a visual inspection. The inspector is not required to program digital thermostats or controls; operate setback features on thermostats or controls; verify the accuracy of thermostats; inspect winterized or decommissioned equipment; inspect for pressure of the systems refrigerant, the type of refrigerant, or for refrigerant leaks; inspect multi-stage controllers, sequencers, or reversing valves; inspect winterized or decommissioned equipment; match tonnage of the interior coils and exterior condensing units; compatibility of components; and the sizing, efficiency, or adequacy of the systems.

### Temperature Differential:

When tested the air temperature differential noted between air supply and air return was 18 degrees left dwelling (3 ton unit) and 20 degrees right dwelling (3 ton unit). (14-20 degree normal range)

## Cooling Equipment Deficiencies:

- Insulation/debris observed at both A/C auxiliary condensate drain pans.
- Penetrations not properly sealed at both evaporator cabinets in the attic. Condensation can form and drip into the auxiliary drain pan if not properly sealed.
- The A/C auxiliary drain lines are not installed at a conspicuous location at the left exterior of the dwelling.



A/C condensing unit labeling





Debris left A/C drain pan

A/C condensing unit labeling




Debris right A/C drain pan

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				



Penetrations not sealed left evaporator



Penetrations not sealed right evaporator

## $\square$ $\square$ $\square$ $\square$ C. Duct Systems, Chases, and Vents

## Comments:

**Note:** The visual inspection of the duct system, chases, and vents does not include internal parts that require dissembling to visually inspect. The condition of the duct system, chases, and vents is based on the performance of the systems when tested and those components that are visually accessible at the time of inspection. Full evaluation of components requiring dismantling of the equipment is beyond the scope of a visual inspection. The inspector is not required to program digital thermostats or controls; inspect duct fans, humidifiers, dehumidifiers, air purifiers, motorized dampers, electronic air filters, multi-stage controllers; inspect winterized or decommissioned equipment; compatibility of components; and the sizing, efficiency, or adequacy of the systems; balanced air flow of the conditioned air to the various parts of the building; types of materials contained in insulation.

## Type of Ducting: Flexible Duct

#### Duct System, Chases, and Vents Deficiencies:

- Separate ductwork where touching at attic to prevent thermal bridging. Thermal bridging causes condensation to form between the duct lines and can drip into the attic.
- No fresh air intake installed at either of the A/C returns. Fresh air intake should be installed at one of the units. Refer to code for fresh air requirements.



Separate ductwork where touching at attic



Separate ductwork where touching at attic

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				
			WELLISTE A M-	



No fresh air intake at A/C return



No fresh air intake at A/C return

## IV. PLUMBING SYSTEMS

## ✓ □ □ ✓ A. Plumbing Supply, Distribution Systems and Fixtures

Location of water meter: Front Exterior

Location of main water supply valve: Front Garage Wall

Static water pressure reading: 72 psi

Type of supply piping material: PEX

Bonding Clamp Location: N/A

Comments:

**Note:** It is not within the scope of this inspection to operate any main, branch or shut-off valves; operate or inspect sump pumps or waste ejector pumps; verify the performance of the bathtub overflow, clothes washing machine drains or hose bibs, or floor drains; inspect any system that has been winterized, shut down or otherwise secured; circulating pumps, free standing appliances, solar water heating systems, water conditioning equipment, filter systems, water mains, private water supply systems, water wells, pressure tanks, sprinkler systems, swimming pools, or fire sprinkler systems; inaccessible gas supply system components for leaks; for sewer clean-outs; or for the presence of performance of private sewage disposal systems; determine the quality, potability, or volume of the water supply; effectiveness of backflow or anti-siphon devices.

## Plumbing Supply, Distribution Systems and Fixtures Deficiencies:

Exposed water lines at the attic are not properly insulated.

☑ Tile grout observed missing under the shower seat at the master bathroom.

☑ Caulk the shower enclosure where missing or deteriorated at the following locations: master bathroom, front guest bathroom.

I=Inspected	NI=Not Inspected	NP=Not Present	<b>D=Deficient</b>	
I NI NP D				




Caulk master shower enclosure



Caulk front guest bathroom shower enclosure



Tile grout missing under master shower seat



Exposed waterlines not insulated at attic

## ☑ □ □ ☑ B. Drains, Wastes, and Vents

*Type of drain piping material:* **PVC Pipe** *Comments:* 

**Note:** It is not within the scope of this inspection to operate any main, branch or shut-off valves; operate or inspect sump pumps or waste ejector pumps; verify the performance of the bathtub overflow, clothes washing machine drains or hose bibs, or floor drains; inspect any system that has been winterized, shut down or otherwise secured; circulating pumps, free standing appliances, solar water heating systems, water conditioning equipment, filter systems, water mains, private water supply systems, water wells, pressure tanks, sprinkler systems, swimming pools, or fire sprinkler systems; inaccessible gas supply system components for leaks; for sewer clean-outs; or for the presence of performance of private sewage disposal systems; determine the quality, potability, or volume of the water supply; effectiveness of backflow or anti-siphon devices.

**Note:** Tub inspection access blocked or none installed and drain connections could not be visually inspected at the following locations: rear guest bathtub, master bathtub.

## Drains, Wastes and Vents Deficiencies:

- The bathroom sink drain stopper is not functioning properly or improperly installed at the following fixtures: front guest bathroom.
- Debris observed in the shower drain line at the following locations: master bathroom.

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				



Debris master shower drain line



Sink stopper not working front guest bathroom

## $\square$ $\square$ $\square$ $\square$ C. Water Heating Equipment

Energy Sources: Gas

Capacity: Tankless

Comments:

**Note:** The temperature and pressure relief test valve was not operated during this inspection due to the possibility of the valve not reseating and water damage resulting. Manufacturers recommend that valves older than three years be removed, cleaned and inspected or replaced. The inspector is not required to verify the effectiveness of the temperature and pressure relief valve, discharge piping, or pan drain pipes; determine the efficiency or adequacy of the unit.

## Water Heater Equipment Deficiencies:


☑ No water shut-off valve installed at the water heater cold water supply line.

☑ The emergency drain pan is not properly positioned under the water heater.

 $\checkmark$  The water heater service platform is inadequate. A minimum 30"x 30" service platform is required at the firebox.



Service platform inadequate front water heater



Water heater pan not position under the unit

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				



No shut off valve at the cold water supply



Water heater labeling

## ✓ □ □ □ D. Hydro-Massage Therapy Equipment

## Comments:

**Note:** The inspector is not required to determine the adequacy of self-draining features of circulation systems.

Hydro-Massage Therapy Equipment Deficiencies:

No indications of defects observed at the time of inspection.

## ☑ □ □ ☑ E. Gas Distribution Systems and Gas Appliances

Location of gas meter: Left Exterior

Type of gas distribution piping material: Black Iron

Bonding Clamp Location: Not properly bonded or could not be verified

Comments:

**Note:** It is not within the scope of this inspection to inspect for sacrificial anode bonding or for its existence; pressurize or test gas system, drip legs or shut-off valves; operate gas line shut-off valves; or light or ignite pilot flames.

## Gas Supply, Distribution Systems and Fixtures Deficiencies:

- ☑ The gas lines are rusted at the following locations: rear patio gas pipe, left exterior at the meter, left furnace at the attic, right furnace at the attic.
- $\square$  Gas odor observed at the water heater in the attic during the inspection. Recommend the plumber be contacted to check for possible leaks.

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			



Gas pipe rusted rear patio



Gas odor at the water heater in the attic



Gas pipe rusted at meter



Gas pipe rusted left furnace in attic



gap pipe rusted right water heater in attic

V.

## APPLIANCES

 Image: Comments:

REI 7-6 (8/9/21)

I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			

**Note:** The dishwasher is operated in normal cleaning mode and heated drying mode when applicable. The inspector is not required to operate and determine the condition of other auxiliary components of inspected items.

## **Dishwasher Deficiencies:**

No loop in drain line or anti siphon device installed to prevent the back flow of contaminated water from sink drain to dishwasher.



No loop dishwasher drain line

## ☑ □ □ ☑ B. Food Waste Disposers

#### Comments:

## Food Waste Disposal Deficiencies:

Disposal connection clamp is not locked into place at the sink flange. Disposal vibration may cause the unit to leak or detach at the sink connection.



Disposal clamp not locked into place

#### ☑ □ □ □ C. Range Hood and Exhaust Systems

Comments:

**Note:** The range exhaust vent is operated in normal mode. The inspector is not required to operate or determine the condition of other auxiliary components of inspected items; determine the adequacy of venting systems; determine proper routing and lengths of duct systems.

Range Exhaust Vent Deficiencies:

*			
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient
I NI NP D			
	No indications of defects	observed at the time of i	inspection.
$\square$ $\square$ $\square$ $\square$ $\square$ $D$ .	Ranges, Cooktops, and Ove	ns	
	Comments:		
		aning function is not inspe ccuracy within 25 degrees.	ected. The oven bake mode is tested at 350
	Ranges, Cooktops, and	Ovens Deficiencies:	
	No indications of defects	observed at the time of i	inspection.
	Microwave Ovens		
	Comments:		
<b>Note:</b> Microwave cooking equipment is not inspected for radiation leaks. The inspector required to operate or determine the condition of other auxiliary components of inspected item.			
	Microwave Oven Deficie	ncies:	
	No indications of defects	observed at the time of i	inspection.
☑ □ □ □ F.	Mechanical Exhaust Vents	and Bathroom Heaters	
	Comments:		
<b>Note:</b> The mechanical exhaust vents and bathroom heaters are operated in normal minspector is not required to operate or determine the condition of other auxiliary comparison inspected items; determine the adequacy of venting systems; determine proper routing a of duct systems.			he condition of other auxiliary components of
	Mechanical Exhaust Ven	ts and Bathroom Heaters	Deficiencies:
	No indications of defects	observed at the time of i	nspection.
☑ □ □ ☑ G.	Garage Door Operators		
	Comments:		
			n the mounted wall switches. The inspector is other auxiliary components of inspected items.
	Garage Door Operator(s	) Deficiencies:	
			Illed at the base of the garage door. The ches above the garage floor.

Garage sensors too high above floor

-	•			
I=Inspected	NI=Not Inspected	NP=Not Present	D=Deficient	
I NI NP D				
Ø□□□н.	<b>Dryer Exhaust Systems</b> <i>Comments</i> :			
	<b>Note:</b> The dryer vent system is visually inspected where accessible. The inspector is not require to operate or determine the condition of other auxiliary components of inspected items; determine the adequacy of venting systems; determine proper routing and lengths of duct systems.			
	<b>Dryer Vents Deficiencies:</b> No indications of defects observed at the time of inspection.			
	VI.	OPTIONAL SYST	•	
	V1.	01 1101AL 5151.		
☑ □ □ ☑ A.	Landscape Irrigation (Sprin Comments:	kler) Systems		
	<ul> <li>Note: The lawn and garden sprinkler system is inspected in manual or service mode only. The inspector is not required to inspect for effective coverage of the irrigation system; automatic function of the controller; the effectiveness of the sensors, such as rain, moisture, wind, flow or freeze sensors; or sizing and effectiveness of backflow prevention device; anything buried, hidden, latent or concealed; operate shut-off valves.</li> <li>Programmable Timer Type and Location: Rainbird - Front Garage Wall</li> <li>Anti-siphon Device Location: Front Exterior</li> <li>Number of Zones Installed: 7</li> <li>Rain Gauge Installed: Yes</li> <li>Shut-off Valve Installed: Not present or could not be verified</li> </ul>			
	Lawn and Garden Sprinkler System Deficiencies:			
	✓ The sprinkler system is not installed with a shut-off valve between the water meter and anti siphon device or could not be located at the time of inspection.			
	The sprinkler controller	interior cover is missi	ng.	
	Sprinkler system winterized	, not operated	Sprinkler interior cover panel missing	

**Note:** The sprinkler system was winterized at the time of inspection. The sprinkler system was not inspected for performance. Only visible deficiencies are notated above if applicable.



## INVOICE

Client: John Doe	INVOICE NUMBER	Inspection Report Sample
	INVOICE DATE	02/13/2023
Mail Payments to:		
A+ Home Inspections		
6786 Cutten Parkway	LOCATION	1234 Anywhere Street
Houston, TX 77069		
Electronic Payments to:		Houston, TX 77000
Zelle Payment to 832-265-8238		
Venmo Payment to @David-Rogers-202		
	REALTOR	

DESCRIPTION	PRICE	AMOUNT
	SUBTOTAL	\$0.00
	TAX	\$0.00
	TOTAL	\$0.00
	BALANCE DUE	\$0.00

## THANK YOU FOR YOUR BUSINESS!

We work very hard to give you the finest quality of service. We feel our business has been successful because of this and you can be sure that anyone you may refer to us will receive the same first class service. You are our valued customer please feel free to call us with any questions you may have about the continuing maintenance and care of your home.

Thanks,

David Rogers T.R.E.C. #5048

Office: 281-440-8901 · Cell: 832-265-8238 · Email: aplushouston@comcast.net · www.aplushomeinspectionstx.com